

Serial No. 09/595,039
Attorney Docket No. E0902
Firm Reference No. AMDSP0379US

Reply to Office Action Dated January 28, 2004
Reply Dated February 25, 2004

AMENDMENTS IN THE DRAWINGS:

Figures 3, 5 and 9 have been amended. In Fig. 3, short lines with arrowheads on both ends as shown in original Fig. 3 have been added to the lines connecting switch 56 to switches 82 and 86, respectively. In Fig. 5, an arrowhead as shown in original Fig. 5 has been added to the line connecting switch 56 to MII interface 62. Additionally, an arrowhead has been added to the line connecting control logic 74 to switch 76 to consistently show the path of the circuit. In Fig. 9, an arrowhead has been removed from the line connecting transmit switch 82 to switch 76 to be consistent with original Fig. 9. No new matter has been added.

Attachment: Three Replacement Sheets




FIG. 3




FIG. 4




FIG. 5




FIG. 8




FIG. 9